

Radiant Panel Insulation Test Update

Presented to: International Aircraft Materials Fire
Test Forum

By: Steve Rehn

Date: 3/5/2019



Federal Aviation
Administration



Introduction

- **Handbook update**
 - Updated June 2018
- **Electric Panel aging testing**
 - Panel runs hotter as it ages, can affect test results
 - Need “borderline” material to test
- **Backing board study**
 - Superwool 607 vs. Fermacell Gypsum Fibreboard



Handbook changes

- **Replaced Superwool 607 with Superwool Plus**
 - All references say “refractory board” with a recommendation of Superwool Plus at the beginning
- **Added requirements:**
 - Maximum thermal conductivity of 0.5 Btu·in/hr·ft²·°F (0.072W/m·K) at 500°F (260°C)
 - Minimum density of 15 lb/ft³ (240 kg/m³)
 - Based on Kaowool M and Superwool 607 since they have been used most
- **This caused problems with other boards that have been used in the past**

Radiant Panel Aging

- Temperature set point steadily increases to obtain same heat flux as panel ages – eventually leads to more material failures
- Biggest difference seems to be black paint on surface
- Need to find out what changes in the panel to make it run hotter
- Need to add guidance about when to replace electric panel

New Panel

Old Panel



Radiant Panel Aging



- Condition likely depends on amount of use and types of materials tested

Radiant Panel Aging


- **Test 7 electric panels**
 - 2 brand new, 1 in use, 4 old out of use
- **Panel set point**
- **3-position calibration check**
- **Measure emissivity of panel surface**
- **Measure internal resistance**
- **Measure power**
- **Measure temperature at sample surface**
- **Material testing**




Metalized PEEK Material

- Received two materials
 - Metalized PEEK with 50% Top Coat
 - Metalized PEEK with No Top Coat


Triumph - Metalized PEEK 50% Top Coat




Triumph - Metalized PEEK 0% Top Coat




FAA - Metalized PEEK 50% Top Coat




FAA - Metalized PEEK 0% Top Coat



DTI - Metalized PEEK 50% Topcoat




DTI - Metalized PEEK 0% Topcoat



More FAA Testing

- Increased heat flux from 1.500 Btu/ft²s to 1.575 Btu/ft²s (+5%)




More FAA Testing

- Installed new panel


- Opened air gaps around drawer
 - Finally got a failure!

	Original	Open
Left	0.375	2.125
Right	0.125	1.875
Rear	2.25	2.25
Front	0	0

FAA - Metalized PEEK 0% Top Coat - New Panel




FAA – Met. PEEK 0% Top Coat - Air Gaps Open



Air Gaps Around Drawer

- **Previously Studied in 2016-2017**
- **2 out of 4 labs showed more failures with gaps closed, other 2 showed no statistical difference**




Triumph Testing


- Installed new panel since previous testing
- Larger air gaps around drawer than FAA Radiant Panel

	Original	1/2" Gaps
Left	2.25	0.5
Right	2.5	0.5
Rear	1	0.5
Front	1.5	0

Triumph - Met. PEEK 50% Top Coat Original Gaps





Triumph - M. PEEK 50% Top Coat - 1/2" Air Gaps




Triumph Testing

- All samples passed when air gaps around drawer were reduced
- In Previous 2016-2017 Study, more samples failed when gaps were closed rather than open



Airflow Around Drawer



- Previously added this drawing to the new rule (not the current handbook)
- Essentially required that area around drawer not be completely closed off
- Do we need to get more specific?
- Gap on right side under panel has larger effect than left side


Backing Board Study

- **Reported problems with certain foam materials that melt and stick to the backing board affecting subsequent tests**
- **Backing board should not interfere with test**
- **Zotefoam organized a study with the FAA and Wulfmeyer**
- **Foam in 25 mm and 3 mm thicknesses**
- **Two different backing boards**
- **3 boards, rotate every test**
- **Melted foam scraped off between tests**
- **30 samples for each combination**




Backing Board Study

	Superwool 607 (67% Silica (SiO ₂), 27% Calcium Oxide + Magnesium Oxide)	Fermacell Gypsum Fibreboard Greenline (Gypsum and Recycled Paper Fibers)
Density (kg/m³)	320 – 350	1150 ± 50
Thermal Conductivity (W/m·K)	0.06 @ 260°C (500°F) (increases with temperature)	0.32 @ 10°C (50°F)




Wulfmeyer Results

25mm Sample - Fermacell



Flame Propagation Average: 1.47 in
 After Flame Time Average: 1.1 s
 Failures: 0


25mm Sample - Superwool



Flame Propagation Average: 1.42 in
 After Flame Time Average: 1.43 s
 Failures: 0


Wulfmeyer Results

Wulfmeyer - 3mm Sample Fermacell



Flame Propagation Average: 0.47 in
 After Flame Time Average: 0.74 s
 Failures: 0


Wulfmeyer - 3mm Sample Superwool



Flame Propagation Average: 0.53 in
 After Flame Time Average: 0 s
 Failures: 0


FAA Results

FAA - 25mm Sample Fermacell



Flame Propagation Average: 1.74 in
 After Flame Time Average: 1.95 s
 Failures: 2

FAA - 25mm Sample Superwool




Flame Propagation Average: 1.68 in
 After Flame Time Average: 2.66 s
 Failures: 13




FAA Results (One board for all tests)

25mm Sample Fermacell - One Board



Flame Propagation Average: 1.71 in
 After Flame Time Average: 2.20 s
 Failures: 4

25mm Sample Superwool - 1 Board



Flame Propagation Average: 1.76 in
 After Flame Time Average: 3.95 s
 Failures: 15



Conclusion

- **Need borderline material to test for panel aging study**
- **Do we need to be more specific for openings around drawer?**
- **Fermacell had higher after flame times for 3 mm sample in Wulfmeyer testing**
- **Superwool had higher after flame times for 25 mm sample in FAA testing**
- **Rotating Fermacell boards did not seem to have an effect**
- **More testing still to be done**

Questions?

Contact:

Steven Rehn
Federal Aviation Administration
William J. Hughes Technical Center
Fire Safety Branch, Bldg. 203
Atlantic City Int'l Airport, NJ 08405
(609) 485-5587
steven.rehn@faa.gov

