

# Radiant Panel Update

**Pat Cahill**  
**AJP-632; Fire Safety Team**  
**Wm. J. Hughes Technical Center**  
**Federal Aviation Administration**



**Federal Aviation  
Administration**



# Radiant Panel

- The last two panels we received were out of specification (found this during the 3-position check and the “very high” set point temperature)
- Both panels were sent back to our distributor who in turn, sent them back to Watlow in St. Louis
- Watlow has informed us that they have replaced the emitter strips on both panels
- It is imperative that a 3-position check be performed when installing a new panel
- Labs should work with their distributors if problems are found